

Sydney Swans Headquarters & Community Centre



Progress Photo Report 2

DATE: 10/09/2021

Project Number: 100390

Address: Royal Hall of Industries, 1 Driver Avenue, Moore
Park NSW

Hoarding install on Lang road

Description
B-Class hoarding installation

Taken Date
10/9/2021 at 09:43 am

Upload Date
10/9/2021 at 09:43 am

Uploaded By
Charlie Akle

File Name
[AFCB2CC7-C475-4D39-9...](#)



Site set up photos


Description
Simpel gate installed ready for usage

Taken Date
10/9/2021 at 09:23 am

Upload Date
10/9/2021 at 09:23 am

Uploaded By
Charlie Akle

File Name
[9B1EFCB2-5811-4553-9...](#)



Site set up photos

Description
Site shed awning
installation

Taken Date
10/9/2021 at 09:22 am

Upload Date
10/9/2021 at 09:23 am

Uploaded By
Charlie Akle

File Name
00AD748F-6A46-4A62-B...



Truss strengthening early works

Description
Roof truss strengthening
works (stage 1) underway

Taken Date
10/9/2021 at 09:22 am

Upload Date
10/9/2021 at 09:22 am

Uploaded By
Charlie Akle

File Name
35E99110-8D21-448C-8...



Truss strengthening early works

Description
Cut outs to field of play ceiling for roof truss strengthening works

Taken Date
10/9/2021 at 09:22 am

Upload Date
10/9/2021 at 09:22 am

Uploaded By
Charlie Akle

File Name
72898E89-11EE-41EA-9...



Hoarding install on Lang road

Description
B-Class hoardings (nightshift)

Taken Date
9/9/2021 at 08:40 pm

Upload Date
9/9/2021 at 08:43 pm

Uploaded By
Chris Tapia

File Name
169831A7-E7E3-42F6-8...



Truss strengthening early works

Description
Ceiling cut outs for roof strengthening works

Taken Date
9/9/2021 at 03:48 pm

Upload Date
9/9/2021 at 03:49 pm

Uploaded By
Charlie Akle

File Name
[7BF7FE90-2075-4995-8...](#)



Truss strengthening early works


Description
Paint stripping sample to roof truss

Taken Date

Upload Date
7/9/2021 at 10:17 am

Uploaded By
Charlie Akle

File Name
[DA27CA22-B42F-4AB4-9...](#)



Truss strengthening early works

Description
Paint stripping sample to roof truss

Taken Date

Upload Date
7/9/2021 at 10:17 am

Uploaded By
Charlie Akle

File Name
[DBAF65BC-85A6-4F34-8...](#)



Site set up photos

Description
Temporary services feed to site sheds

Taken Date
6/9/2021 at 01:11 pm

Upload Date
6/9/2021 at 03:11 pm

Uploaded By
Charlie Akle

File Name
[C704AB39-FAEC-435F-8...](#)



Pre Construction - General Site Photos

Description
Site fencing installed

Taken Date
6/9/2021 at 10:22 am

Upload Date
6/9/2021 at 10:22 am

Uploaded By
Charlie Akle

File Name
[EE5BF25D-BCDF-45BC-B...](#)



Pre Construction - General Site Photos

Description
Temp power line to site shed

Taken Date
6/9/2021 at 10:19 am

Upload Date
6/9/2021 at 10:19 am

Uploaded By
Charlie Akle

File Name
[AB7F1DFD-925B-403F-B...](#)

