

## Sydney Swans Headquarters & Community Centre



### Progress Photo Report 14

*DATE: 03/12/2021*

Project Number: 100390

Address: Royal Hall of Industries, 1 Driver Avenue, Moore  
Park NSW



### Site Walk 3/12/21

Description  
Storm water connection  
works

Taken Date  
3/12/2021 at 09:53 am

Upload Date  
3/12/2021 at 10:07 am

Uploaded By  
Dylan Luisi

File Name  
[BB647BDA-DCD7-468B-...](#)



### Site Walk 3/12/21

Description  
Detailed excavation and  
storm water connection

Taken Date  
3/12/2021 at 09:52 am

Upload Date  
3/12/2021 at 10:07 am

Uploaded By  
Dylan Luisi

File Name  
[44C2F033-F733-4230-8...](#)





### Site Walk 3/12/21

#### Description

Footing reinforcement  
installation ready for  
concrete pour

#### Taken Date

3/12/2021 at 09:50 am

#### Upload Date

3/12/2021 at 10:20 am

#### Uploaded By

Dylan Luisi

#### File Name

[2D18C691-DCC3-4E1A-...](#)



### Site Walk 3/12/21

#### Description

Reinforcement installation  
to pour B

#### Taken Date

3/12/2021 at 09:38 am

#### Upload Date


3/12/2021 at 10:20 am

#### Uploaded By

Dylan Luisi

#### File Name

[DEBA51A6-D2F5-458F-9...](#)





### Site Walk 3/12/21

Description  
Lift shaft formwork &  
scaffold installation

Taken Date  
3/12/2021 at 09:35 am

Upload Date  
3/12/2021 at 10:20 am

Uploaded By  
Dylan Luisi

File Name  
[BC60DE5F-B5A1-423A-A...](#)



### Site Walk 3/12/21


Description  
Shoring walls placed for  
storm water connections

Taken Date  
2/12/2021 at 02:30 pm

Upload Date  
3/12/2021 at 10:31 am

Uploaded By  
Dylan Luisi

File Name  
[fdcswansext\\_20211202\\_...](#)





### Site Walk 3/12/21

#### Description

Storm water excavation  
and soil removal

#### Taken Date

2/12/2021 at 08:30 am

#### Upload Date

3/12/2021 at 10:30 am

#### Uploaded By

Dylan Luisi

#### File Name

[fdcswnsxt\\_20211202\\_...](#)



### Site Walk 3/12/21

#### Description

Soil removal from lift pits  
excavation & pour B  
services rough in

#### Taken Date

2/12/2021 at 08:04 am

#### Upload Date


3/12/2021 at 10:30 am

#### Uploaded By

Dylan Luisi

#### File Name

[fdcswnsint\\_20211202\\_...](#)





### Site Walk 3/12/21

Description  
Crane lift for redundant  
AHU's removal

Taken Date  
1/12/2021 at 04:00 pm

Upload Date  
3/12/2021 at 09:23 am

Uploaded By  
Dylan Luisi

File Name  
[BBA87D78-18B5-46D9-...](#)



### Site Walk 3/12/21

Description  
Detailed excavation pool  
area for Storm water  
works

Taken Date  
1/12/2021 at 11:15 am

Upload Date  
3/12/2021 at 10:30 am

Uploaded By  
Dylan Luisi

File Name  
[fdcswansext\\_20211201\\_...](#)





### Site Walk 3/12/21

Description  
Crane lift for redundant  
AHU's removal

Taken Date  
1/12/2021 at 10:29 am

Upload Date  
3/12/2021 at 09:23 am

Uploaded By  
Dylan Luisi

File Name  
[DF790835-4D75-4927-B...](#)



### Site Walk 3/12/21

Description  
RHI formwork drop off for  
pour C

Taken Date  
1/12/2021 at 09:34 am

Upload Date  
3/12/2021 at 10:30 am

Uploaded By  
Dylan Luisi

File Name  
[fdcswansint\\_20211201\\_...](#)





### Site Walk 3/12/21

#### Description

Bulk excavation to pool area

#### Taken Date

29/11/2021 at 04:15 pm

#### Upload Date

3/12/2021 at 10:30 am

#### Uploaded By

Dylan Luisi

#### File Name

[fdcswansext\\_20211129\\_...](#)



### Site Walk 3/12/21

#### Description

Soil removal from excavation works to lift pit's

#### Taken Date

29/11/2021 at 11:04 am

#### Upload Date

3/12/2021 at 10:30 am

#### Uploaded By

Dylan Luisi

#### File Name

[fdcswansint\\_20211129\\_...](#)

