

Sydney Swans Headquarters & Community Centre



Progress Photo Report 17

DATE: 14/01/2022

Project Number: 100390

Address: Royal Hall of Industries, 1 Driver Avenue, Moore
Park NSW

Site Walk (14/01/22)

Description
Pour B formwork
dismantle and services
rough in commencement

Taken Date
14/1/2022 at 11:11 am

Upload Date
14/1/2022 at 11:23 am

Uploaded By
Dylan Luisi

File Name
[BC47D18F-F664-478B-8...](#)



Site Walk (14/01/22)


Description
Pour C reinforcement
installation

Taken Date
14/1/2022 at 11:11 am

Upload Date
14/1/2022 at 11:23 am

Uploaded By
Dylan Luisi

File Name
[334DCE54-B8F5-4A29-9...](#)



Site Walk (14/01/22)

Description
Pour D formwork
installation

Taken Date
14/1/2022 at 11:11 am

Upload Date
14/1/2022 at 11:23 am

Uploaded By
Dylan Luisi

File Name
[1C5E988B-A54E-4EDC-9...](#)



Site Walk (14/01/22)

Description
Existing trusses painted
(white)

Taken Date
14/1/2022 at 10:46 am

Upload Date
14/1/2022 at 11:24 am

Uploaded By
Dylan Luisi

File Name
[3663B99D-17BA-46C3-8...](#)



Site Walk (14/01/22)

Description
wailing beams installed to
support the existing
heritage wall for the
basement excavation

Taken Date
14/1/2022 at 10:46 am

Upload Date
14/1/2022 at 11:27 am

Uploaded By
Dylan Luisi

File Name
[2E09503D-D5B4-40A2-8...](#)



Site Walk (14/01/22)

Description
Medical tenancy perimeter
wall stud & track
installation

Taken Date
14/1/2022 at 10:43 am

Upload Date
14/1/2022 at 11:27 am

Uploaded By
Dylan Luisi

File Name
[ECF6CABE-EAFA-447B-A...](#)



Site Walk (14/01/22)

Description
Field of Play trusses
painting

Taken Date
14/1/2022 at 10:26 am

Upload Date
14/1/2022 at 11:39 am

Uploaded By
Dylan Luisi

File Name
[3B734D4D-1B47-4ECF-9...](#)



Site Walk (14/01/22)

Description
Pour B services rough-in

Taken Date
14/1/2022 at 10:25 am

Upload Date
14/1/2022 at 11:39 am

Uploaded By
Dylan Luisi

File Name
[D630EC9A-E1B2-4946-9...](#)



Site Walk (14/01/22)

Description
Stormwater detailed
excavation works

Taken Date
14/1/2022 at 10:24 am

Upload Date
14/1/2022 at 11:39 am

Uploaded By
Dylan Luisi

File Name
[64D80393-4ED7-4340-9...](#)



Site Walk (14/01/22)

Description
Swifts existing slab
demolition

Taken Date
14/1/2022 at 10:18 am

Upload Date
14/1/2022 at 11:44 am

Uploaded By
Dylan Luisi

File Name
[072FBBFC-EA19-47D5-9...](#)



Site Walk (14/01/22)

Description
RHI painting field of play
trusses

Taken Date
14/1/2022 at 09:49 am

Upload Date
14/1/2022 at 11:59 am

Uploaded By
Dylan Luisi

File Name
[fdcskansint_20220114_...](#)



Site Walk (14/01/22)

Description
Stormwater excavation
and existing slab
demolition works

Taken Date
13/1/2022 at 11:45 am

Upload Date
14/1/2022 at 11:59 am

Uploaded By
Dylan Luisi

File Name
[fdcskansext_20220113_...](#)



Site Walk (14/01/22)

Description
RHI existing truss painting
works

Taken Date
13/1/2022 at 09:34 am

Upload Date
14/1/2022 at 11:59 am

Uploaded By
Dylan Luisi

File Name
[fdcskansint_20220113_...](#)



Site Walk (14/01/22)

Description
Stormwater excavation
works

Taken Date
12/1/2022 at 12:30 pm

Upload Date
14/1/2022 at 11:59 am

Uploaded By
Dylan Luisi

File Name
[fdcskansext_20220112_...](#)



Site Walk (14/01/22)

Description
Pour D formwork
installation

Taken Date
11/1/2022 at 12:19 pm

Upload Date
14/1/2022 at 11:59 am

Uploaded By
Dylan Luisi

File Name
[fdcskansint_20220111_...](#)



Site Walk (14/01/22)

Description
Stormwater excavation
works

Taken Date
10/1/2022 at 09:30 am

Upload Date
14/1/2022 at 11:59 am

Uploaded By
Dylan Luisi

File Name
[fdcskansext_20220110_...](#)

